V	Torres of health an	Course of cultures	D. T.Para addison	Location	Building	Building	No of	No of
Year	Type of building	Causes of collapse	Building address	area	status	information	storey	casualty
2000	commercial	structural defect	Eleganza Building, Ikota, Ajah	island	completed	occupied	0	25
2000	commercial	structural defect	St. Dennis Catholic Church, Bariga	mainland	completed	occupied	0	3
2000	commercial	overload	State High School, Alimosho	mainland	completed	occupied	2	2
2000	commercial	structural error	Folami Pry School, Atunrase, Surulere	mainland	completed	occupied	1	2
2000	residential	structural defects	14, Semi Sarumi Street, Itire, Surulere	mainland	completed	occupied	1	1
2000	residential	structural defect	10/12, Suenu Street, Lagos Island	island	completed	occupied	0	2
2000	residential	flood	12A, Okedeji Lane, Lagos	mainland	completed	occupied	0	0
2000	residential	flood	14, Ogba Road, Agege	mainland	completed	occupied	0	0
2000	residential	structural defect	1, Olorishade Street, Agege	mainland	completed	occupied	0	0
2000	residential	structural defect	Isako Village, off Lekki-Epe Highway	island	completed	occupied	0	5
2001	commercial	structural defect	Karunwi Central Mosque, 21 Buhari Street, Mushin	mainland	completed	occupied	0	7
2001	residential	structural defect	15, Akewusola Street, Oworonsoki	mainland	completed	occupied	0	1
2002	residential	structural defect	20, Otigba Street, off Pabble Street, Ikeja	mainland	completed	occupied	0	41
2002	residential	structural defect	Mosadolohun Street, Iba	mainland	completed	occupied	3	15
2002	residential	structural defect	12, Fredrick Faseun Avenue, Okota, Isolo	mainland	completed	occupied	0	15
2002	residential	structural defects	Agege Road	mainland	completed	occupied	0	0
2002	residential	structural defects	Allen Avenue, Ikeja	mainland	completed	occupied	2	0
2002	residential	structural defects	10, Jones Street, Ebute Metta West	mainland	completed	occupied	0	0
2002	residential	structural defects	49, Olonode Street, Yaba	mainland	completed	occupied	0	0
2002	residential	structural defects	Isiaka Street, off Agege Road	mainland	completed	occupied	0	0
2003		structural defect	50 Willoughby Street, Ebute Metta	mainland	completed	occupied	1	0
2003	commercial	local explosion	28 Idumagbo Avenue, Island	island	completed	occupied	3	90
2003	commercial	local explosion	Pedro Street, near Idumagbo Avenue, Lagos Island	island	completed	occupied	3	0

2003	commercial	structural defect	Bereka Lane, Lagos	mainland	uncompleted	unoccupied	3	0
2003		structural defect	Adeniji Adele Road, lagos island	island	unreported	unreported	0	0
2003	residential	construction defect	118, Ojuelegba Road	mainland	unreported	unreported	0	0
2004	commercial	structural defect	22, Markurdi Street, Ebute Metta	mainland	completed	occupied	3	0
2004	residential	sub-standard material	Ilasamaja Mushin	mainland	unreported	unreported	2	0
2004	residential	poor maintenance	10, Elias Street, Lagos Island	island	completed	occupied	2	0
2005	residential	structural defect	40, Market Street, Shomolu	mainland	unreported	unreported	2	0
2005	residential	structural defect	Kodesho/Bank-Anthony Way	mainland	unreported	unreported	2	0
2005	commercial	structural defect	Adeniji Adele, Lagos Island	island	uncompleted	unoccupied	3	0
2005	commercial	sub-standard material	6, Princess Street, Lagos Island	island	unreported	unreported	3	0
2005	residential	structural defect	lponri, surulere, Lagos	mainland	unreported	unreported	0	0
2005	residential	structural defect	Richard Abimbola Street, Ilasamaja, Lagos	mainland	uncompleted	unoccupied	2	0
2006	commercial	structural defect	53, Cemetery Road, Amukoko	mainland	complete	occupied	4	0
2006	commercial	structural defect	ljora, Ajegunle	mainland	complete	occupied	3	0
2006	commercial	fire accident	NIDB Building, Broad Street, Lagos Island	island	complete	occupied	21	24
2006	commercial	structural defect	71, Ibadan Street, Ebute Metta West	mainland	complete	occupied	3	0
2006		structural defect	38, Idumagbo Avenue, Lagos Island	island	unreported	unreported	0	0
2006	commercial	structural defect	42, Ibadan Street, Ebute Metta East	mainland	complete	occupied	3	0
2006	residential	structural defect	8, Ashaka Street, Abule-Nla, Ebute Metta	mainland	unreported	unreported	2	0
2006	residential	structural defect	 Murtala Muhammed Airport Road Oshodi 	mainland	complete	occupied	2	4
2006	commercial	poor maintenance	6A Milverton Close, Ikoyi	island	uncompleted	occupied	3	0
2007	residential	structural defect	118, Ojuelegba, Surulere	mainland	complete	occupied	2	0
2007	residential	structural defect	LASU-Iba road opp. Rosellus	mainland	complete	occupied	2	0
2007	commercial	structural defect	48, Adams street	island	complete	occupied	3	0
2007	commercial	structural defect	38, Idumagbo Avenue	Island	unreported	unreported	3	0

2007 2007 2008	commercial residential commercial	structural defect structural defect non-compliance with specification	32B Egerton lane, oke Arin 71, Aguro street Ogudu Ojota	island island mainland	unreported unreported completed	unreported unreported occupied	4 3 22	0 0 0
2009 2010	residential residential	unreported sub-standard material	lagos Isopako, Odowo Street, Cairo, Oshodi	mainland mainland	unreported uncompleted	unreported unoccupied	2 0	7 16
2010	residential	sub-standard material	Adenike Street, Off New Market, Oniru Estate, Victoria Island	island	uncompleted	unoccupied	0	3
2010	commercial	structural defect	24, Alli Street, off Tinubu Street, Victoria Island,	island	completed	occupied	4	3
2011	commercial	unreported	Adenubi Close Ikeja	mainland	completed	occupied	5	0
2011	residential	unreported	Idumota	mainland	completed	occupied	4	6
2011	residential	unreported	Doyin Omololu street, Ketu	mainland	uncompleted	unoccupied	1	2
2011	commercial	unreported	Aderibigbe Street Maryland	mainland	completed	occupied	5	0
2011	residential	unreported	Haano Industries Limited on Oba Akran Road, Ikeja	mainland	completed	occupied	0	0
2011	residential	unreported	school building in Badagry	mainland	completed	occupied	0	0
2011	commercial	unreported	Lagos state secretariat, ikeja	mainland	completed	occupied	0	7
2011	commercial	no geotechnical information	11, Aderibigbe Street, maryland, lagos	mainland	completed	occupied	5	0
2011	residential	non-adherence to building standard and regulation	Oloto Street, off Cemetery Road, Ebute Metta, Lagos	island	completed	occupied	3	24
2011	residential	bad supervision	Orosanye Street, Lagos.	island	completed	occupied	3	4
2012	residential	structural defect	Jakande estate Oke-Ake Afa, Isolo, Lagos	mainland	completed	occupied	2	0
2012	commercial	unreported	49 Freeman Street, Oyingbo	mainland	completed	occupied	8	0
2012	commercial	unreported	11 Anikantamo Street, Off Adeniji-Adele, in Ita Faji, Lagos Island	island	completed	occupied	6	0
2013	commercial	unreported	Victoria Island, Lagos	island	uncompleted	unoccupied	1	3
2014	residential	demolition process	Ikotun-Egbe area of Lagos state	mainland	uncompleted	unoccupied	3	29
2014	commercial	structural defect	Ikotun-Egbe area of Lagos state	mainland	completed	occupied	4	140

2015	residential	unreported	6 Mogaji Street Idumota Lagos island	island	completed	occupied	3	4
2015	residential	structural defect	Ebuta-metta Lagos	island	completed	occupied	1	1
2015	residential	structural defect	Swamp street, Odunfa Lagos island.	island	completed	occupied	5	0
2015	residential	bad supervision	Sunny filled, FlourMills, Estate, Magbon, Badagry, Lagos	mainland	uncompleted	unoccupied	3	0
2016	commercial	onsite change of plan	Horizon 1, Lekki, Garden, Ikate	island	uncompleted	unoccupied	1	9
2016	both	structural defect	53 Massey Street, Ita Faaji, Lagos Island	island	completed	occupied	4	47
2016	residential	structural defect	Lekki, Lagos	island	uncompleted	unoccupied	0	60
2017	residential	structural defect	Richard Abimbola Street, Ilasamaja, Lagos	mainland	uncompleted	unoccupied	2	0
2017	both	unreported	3, Massey Street on Lagos Island	island	completed	occupied	0	23
2018	residential	structural defect	 community road, off old otta road Alagbado 	mainland	completed	occupied	3	5
2018	residential	structural defect	No. 9, Abeje Street Markaz, Agege.	mainland	completed	occupied	3	1
2019	residential	unreported	Lagos Island	island	completed	occupied	3	0
2019	residential	onsite change of plan	53 Massey Street, Ita Faaji, Lagos Island	island	completed	occupied	3	60
2020	residential	structural defect	Freeman Street, Lagos Island.	island	completed	occupied	3	12
2021	residential	structural defect	No. 19 Church Street, off	island	completed	occupied	3	1
2021	commercial	sub-standard material	Adeniji Adele Street, Lagos Island. No. 19 Church Street, off Adeniji Adele Street, Lagos Island.	island	uncompleted	unoccupied	21	61