Spherical void formers in concrete slabs

C C Marais, J M Robberts, B W J van Rensburg

ERRATA

An error appeared in Figure 11 on page 10. The correct figure looks as follows:




Figure 11 Cost comparison of SVF, coffer and post-tensioned slabs in South Africa for a distributed 2,5 kPa additional dead load and 2,5 kPa live load

ERRATA

JOURNAL OF THE SOUTH AFRICAN INSTITUTION OF CIVIL ENGINEERING

Vol 53 No 1, April 2011, Page 63, Paper 738

Publication particulars of paper being corrected: Vol 52 (2) 2010, pp 2–11, Paper 738