


Repairs to the "pregnant oyster" in Strijdom Square, graphically illustrated. 1. Cables through the two-tier parking garage to the concrete foundations moor the cupola. 2. A copper covering worth R20 000 has been placed over it to hide cracks in the cupola into which water leaked and bind the structure. 3. The "cables" that are tied to the foundations girdle the cupola.



Rand Daily Mail 23 Nov. 1979